

Latitudes, Departures and Closing Errors.

Line Designated	True Bearing	Dist.	Latitudes		Departures	
			N.	S.	E.	W.
S. Bdy. T34NR50E	West	457.94				457.94
W. " " "	N.0°26'W	164.04	164.04			1.21
W. " " "	N.0°28'E	39.46	39.46		.33	
W. " " "	N.0°9'E	40.62	40.62		.10	
W. " " "	N.0°01'E	40.16	40.16		.01	
W. " " "	N.0°22'E	40.12	40.12		.25	
W. " " "	N.0°55'W	81.80	81.79			1.28
W. " " "	N.0°34'E	40.29	40.29		.40	
W. " " "	N.0°13'E	40.36	40.36		.15	
N. " " "	East	382.48			382.48	
E. " " "	S.0°4'W.	16.28		16.28		.02
E. " " "	S.0°1'E	79.88		79.88		.02
E. " " "	S.0°24'E	79.69		79.69		.56
E. " " "	South	242.94		242.94		
S. " T34NR51E	East	76.27			76.27	
E. " T34NR50E	S.0°14'W	68.60		68.60		.28
Convergency					.51	
		Totals	486.84	487.39	461.08	460.73
				486.84	460.73	
		Error in lat.		.55	.35	Er. in Dep.

GENERAL DESCRIPTION.

This township contains nearly every variety of land from rolling valley to high mountain peaks.

The soil is clay and gravelly loam and richest along the bottoms of the hollows and ravines and the east edge of **Boulder** valley. There is in general a clay and gravelly hard pan for subsoil from 1 to 2 ft. below surface except the portions which have a solid rock subsoil, which, in general is the high mountain peaks.

The entire township is covered with a dense growth of sagebrush from 1 to 3 ft. high about 2½ ft. average; and is also covered with rich and nutritive native grasses which make it very valuable for grazing purposes.

Dry farming could probably be profitably done in the following sections; part of sec. 2 and sec. 6; secs. 7, 18, 19, 30 and 8, and part of secs. 17, 20, 29 and 31.

There is a small stream of water, which, during the early spring, runs entirely thru the township in the southern portion, but later in the season it runs only thru secs. 34, 35 and 27. There is no other water in the township except a well in sec. 2, at the Richmond cabin.

Prospecting for mineral has been done in secs. 2, 3, and 10, but no mineral in sufficient quantities for commercial purposes has been found so far as we could learn.

There are no settlers in the township, except miners who occasionally occupy the Richmond cabin in sec. 27.

A new telephone line has recently been constructed entirely across the southern portion of the township by the Pacific States Telephone and Telegraph Company.

There is an old corral in the southeast part of sec. 29, and a wire corral near the center of sec. 29, the former is practically demolished but the latter is used for round up purposes by various cattle men.

There is no timber in the township except a few aspens in secs. 34 and 35 along the spring branches. Some wood