

8. Fractional N. Bdy. T.34 N., R. 57 E.

Chains	
40.00	Descend SW. slope. 45 ft. below ridge. Set an iron post 3 ft. long, 1 in. in dia., 24 ins. in the ground for the $\frac{1}{4}$ sec. cor. for sec. 6, with brass cap mkd: $\frac{1}{4}$ <u>S 6</u> 1915 dig pits 18x18x12 ins. E. and W. of cor. 3 ft. dist., and raise a mound of earth $3\frac{1}{2}$ ft. base, $1\frac{1}{2}$ ft. high, S. of cor.
49.70	Ravine, course SE. Ascend NE. slope.
81.30	85 ft. above ravine. The cor. of Tps. 34 and 35 N., R. 57 E., described on p. 5. Land, rolling with a general SE. slope. Soil, dry, sandy and gravelly, desert loam, 2nd rate. Too dry for cultivation. Good growth of sagebrush, considerable grass, weeds and other browse. No timber.
	Oct. 22, 1915.

BOUNDARIES OF FRAC. T.34 N., R.57 E.
LATITUDES, DEPARTURES AND CLOSING ERRORS.

Line Designated	True Bearing	Dist.	Latitudes		Departures	
			N.	S.	E.	W.
		chs.	chs.	chs.	chs.	chs.
W.Bdy.of Tp.	South	239.65		239.65		
S.Bdy.sec.18	East	81.21			81.21	
E.Bdy.sec.18-7	N.0°05'E.	159.14	159.14		.22	
S.Bdy.sec.5	S.89°51'E.	80.41		.22	80.41	
E.Bdy.sec.5	N.0°11'W.	80.39	80.39			.26
N.Bdy.of Tp.	West	161.71				161.71
Convergency						.07
			239.53	239.87	161.84	162.04
				239.53		161.84
		Error in lat.		.34	Er.in dep.	.20

GENERAL DESCRIPTION.

This fractional township is made up of rolling hills, low ridges, and shallow ravines and washes, all with a general SE. slope.

The soil is a sandy, medium texture desert loam, derived from the disintegration of sedimentary rocks, varying in depth from a few inches on the hill slopes to several feet in the bottoms of the draws. It is a good quality soil, but too dry to raise crops without irrigation, and it does not seem possible to get water from any source to irrigate it.

It is a very fair grazing country, there being a good growth of sagebrush and considerable grass, weeds and other browse. It, and the surrounding country is poorly watered, though, there being no water in this fractional township.

There are no settlers. There is no land in cultivation in this fractional township nor any in cultivation nearby.

There is no timber.

October 22, 1915.

Winfred A. Pray
U.S. Surveyor.