


Resurvey of fractional E. bdy. T 21 N, R 29 E.

Chains

Begin at the cor. of secs. 25, 30, 31 and 36: on the E. bdy. of the tp.

Reestablish this cor. as follows:

At the same point set an iron post, 3 ft. long, 2 ins. dia., 24 ins. in the ground for cor. of secs., 25, 30, 31 and 36, with brass cap mkd.



1916

dig pits 18 x 18 x 12 ins. in each sec., 5 1/2 ft. dist.

and set old cor. alongside of post.


N 0°49'E, bet. secs. 25 and 30.

40.06 The old 1/4 sec. cor.

Reestablish this cor. as follows:

At the center of the mound of earth,

Set an iron post, 3 ft. long, 1 in. dia., 24 ins. in the ground for 1/4 sec. cor., with brass cap mkd.



dig pits 18 x 18 x 12 ins. N. and S. of post, 3 ft. dist.


and set old cor. alongside of post.

Thence N 0°24'E

30.30 Point for cor. of secs. 19, 24, 25 and 30; falls in slough, not set.

N 0°24'E, bet. secs. 19 and 24.

2.54 Set an iron post, 3 ft. long, 2 ins. dia., 24 ins. in the ground for witness corner for secs. 19, 24, 25 and 30; with brass cap mkd.



dig pits 18 x 18 x 12 ins. in each sec., 5 1/2 ft. dist.