4.

Chains 80.00

The point for the cor. of secs. 25,30,31 and 36 which falls on the N. edge and slope of exposed quartzite ledge where it is impossible to establish a permanent corner. Land, rough, broken mountains. Soil; heavy clayey loam, rocky, outcropping ledges, lime. Grazing land. Undergrowth; sage brush, bunch grass, service brush, Scattering junipers. Not being on the meridian at noon, took no observation for latitude.

.50

S. on a true line bet. secs. 31 and 36. Descend along a steep S. slope of spur. Set an iron post, 3 ft. long, 3 ins. diam., 20 ins. in the ground to solid rock and in a mound of stone for the witness corner of the corner of secs. 25, 30, 31 and 36, with brass cap mkd., T27N

13.00

and raise a mound of stone 2 ft. base, 12 ft. high W. of corner.

20.00 26.00 Head of ravine, running water, drains W. Spring W. 2 chs. Creek 2 lks. wide, 4 ins. deep, course N. 50°W.

Creek 4 lks. wide, 4 ins. deep, course N. 40°W.

Ascend N. slope of steep mountain.

Set an iron post, 3 ft. long, 1 in. diam., 26 ins.
the ground for 4 sec. cor., with brass cap mkd.,

40.00

and raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high W. of corner.

Top of a ridge, 860 ft. above creek, bears N. 80°W. and

49.41

S. 80°E. Descend S. slope over high rocky cliffs.

73.00

Jersey Creek, 2 lks. wide, 2 ins. deep, 725 ft. below ridge, course N: 70°W.
Ascend N. slope of ridge.

80.00

Set an iron post, 3 ft. long, 3 ins. diam., 24 ins. in ground, for the cor. of Tps. 26 and 27 N., Rs. 40 and ground, for one cap mkd.,
41 E with brass cap mkd.,
T27N

Raise a mound of stone, 2 ft. base, l ft. high S. of cor, This corner is on N. slope. Land, high rough mountains. Soil; rocky, heavy clay loam. Rock outcrops, ledges and cliffs. Undergrowth; sage and service brush, bunch grass. Timber, scattering growth of junipers.

June 14, 1915.