

S.

West Boundary of T. 24 N., R. 48 E.

Chains

57.30

80.00

Dig pits, 18x18x12ins, N. and S. of post 3 ft. dist., and raise a mound of earth  $3\frac{1}{2}$  ft. base,  $1\frac{1}{2}$  ft. high W. of corner.

Enter low clay hummocks, bearing N.  $45^{\circ}$  E. and S.  $45^{\circ}$  W.

Set an iron post, 3 ft. long, 3 ins. diam., 24 ins. in the ground for cor. of secs. 7, 12, 13 and 18, with brass cap mkd.,

T24N  
R47E : R48E  
S12 : S7  
S13 : S18

1915

Dig pits, 18x18x12ins, in each sec.  $5\frac{1}{2}$  ft. dist., and raise a mound of earth 4 ft. base, 2 ft. high W. of corner.

Land, dry and level alkali lake bed.

Soil, heavy green clay, moist and alkaline.

No vegetation.

40.00

N. bet. secs. 7 and 12.

Leave low clay hummocks, bearing N.  $45^{\circ}$  E. and S.  $45^{\circ}$  W. and cross open lake bed.

Set an iron post 3 ft. long, 1 in. diam., 26 ins. in the ground for  $\frac{1}{2}$  sec. cor., with brass cap mkd.,

S12 $\frac{1}{2}$  : S7

1915

80.00

dig pits, 18x18x12ins, N. and S. of post 3 ft. dist., and raise a mound of earth  $3\frac{1}{2}$  ft. base,  $1\frac{1}{2}$  ft. high W. of corner.

Set an iron post 3 ft. long, 3 ins. diam., 24 ins. in the ground for cor. of secs. 1, 6, 7 and 12, with brass cap mkd.,

T24N  
R47E : R48E  
S1 : S6  
S12 : S7

1915

dig pits, 18x18x12ins, in each sec.  $5\frac{1}{2}$  ft. dist., and raise a mound of earth 4 ft. base, 2 ft. high W. of cor.

Land, level dry lake bed.

Soil, heavy green clay, moist and alkaline.

No vegetation.

40.00

N. bet. secs. 1 and 6.

Over level barren lake bed.

Set an iron post 3 ft. long, 1 in. diam., 26 ins. in the ground for  $\frac{1}{2}$  sec. cor., with brass cap mkd.,

S1 $\frac{1}{2}$  : S6

1915

80.00

dig pits, 18x18x12ins, N. and S. of post 3 ft. dist., and raised a mound of earth  $3\frac{1}{2}$  ft. base,  $1\frac{1}{2}$  ft. high W. of corner.

Set an iron post 3 ft. long, 3 ins. diam., 24 ins. in the ground for cor. of T. 24 N., 24 and 25 N., R. 47 and 48 E. with brass cap mkd.,