

Chains

Note:-

Owing to the duplexity of corners in previously existing erroneous surveys of T. 16 S., R. 56 E.; the SW $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 11, entered by Franklin Eddy is in conflict with SE $\frac{1}{4}$ NW $\frac{1}{4}$ sec. 16, originally state land and now owned by Ira Mac Farland.

Tract No. 45.


The W $\frac{1}{2}$ SW $\frac{1}{4}$ sec. 11. 80 acres

Entryman--- Franklin Eddy, part of HD. 08960, Valid.

On line 3-4 TR. 44, 17.50 chs. west of cor. No. 4 TR. 44, hereinbefore described.

Set an iron post 3 ft. long, 1 in. diam., 26 ins. in the ground for cor. No. 1 of TR. 45, with brass cap mkd.

T16S R56E



1917


Thence,

West on line 1-2 TR. 45.

20.00

Set an iron post 3 ft. long, 1 in. diam., 26 ins. in the ground for cor. No. 2 of TR. 45, identical with cor. No. 1 of TR. 46, with brass cap mkd.

T16S R56E



1917

Thence

South on line 2-3 TR. 45.