

Closings of T. 43 N., R. 35 E.

Boundaries of T. 43 N., R. 35 E.

Latitudes, Departures and Closing Errors							
Line Designated	True Bearing	Distance	Latitudes		Departures		
			N.	S.	E.	W.	
			Chs.	Chs.	Chs.	Chs.	
East Bdy.	North	478.07	478.07				
North Bdy.	West	463.24				463.24	
	North	3.70	3.70				
	West	23.86				23.86	
West Bdy.	South	482.50		482.50			
South Bdy.	East	487.68			487.68		
Convergency.....							.64
			481.77	482.50	487.68	487.74	
				481.77		487.68	
Error in Latitude.....				0.73			
Error in Departure.....						0.06	

GENERAL DESCRIPTION

This township lies mainly in the Double H mountains, a range that lies between the Quinn River and King River valleys. The extreme western portion lies in the Eastern part of the King River Valley, breaking off abruptly from the table land which comprises part of the said range.

This western portion is quite barren. The soil is a light compact clay loam of good depth, slightly alkaline, free from rock. It sustains an abundant growth of greasewood, but no water or timber. The balance of the township is rolling and broken mountains, fairly watered by small springs. It sustains a good growth of sagebrush, bunch-grass and deer brouse and is excellent grazing land.

There are no indications of mineral in the township.

Ignacio ~~Leiz~~ is the only settler; he has a small place fenced, in the $SE\frac{1}{4}SE\frac{1}{4}$, sec. 12.

John R. English

U. S. Transitman

Samuel R. Mercer

U. S. Transitman