

Establishment of the  $\frac{1}{4}$  Sec. Cors. on the W. Bdy. of T. 44 N., R. 58 E.

Chains

 $\frac{1}{4}$   
S 6.

1935

raise a mound of stone,  $2\frac{1}{2}$  ft. base,  $1\frac{1}{2}$  ft. high, E. of cor.

Deposit an igneous rock,  $3 \times 4 \times 4\frac{1}{2}$  ins., mkd. with a cross (X), at base of post.

NORTH BOUNDARY OF T. 44 N., R. 58 E.  
QUARTER SECTION COR. ON N. BDY. OF SEC. 1

From the  $\frac{1}{4}$  sec. cor. of sec. 36, T. 45 N., R. 58 E., heretofore described; West, 4.98 chs. dist.

To a point 40.00 chs. East of the closing cor. of secs. 1 and 2.

Set an iron post, 3 ft. long, 1 in. diam., on solid rock, and in a mound of stone to top of post, for the  $\frac{1}{4}$  sec. cor. of sec. 1 only, with brass cap mkd.

 $\frac{1}{4}$  S 1.

1935

from which

A pine, 8 ins. diam., bears S.  $5^\circ$  W., 40 lks. dist., mkd.  $\frac{1}{4}$ S1BT.

QUARTER SECTION COR. ON N. BDY. OF SEC. 2

From the  $\frac{1}{4}$  sec. cor. of sec. 35, T. 45 N., R. 58 E., heretofore described; West, 5.215 chs. dist.

To a point midway bet. the closing cor. of secs. 1 and 2, and the closing cor. of secs. 2 and 3.

Set an iron post, 3 ft. long, 1 in. diam., 20 ins. in the ground, to solid rock, and in a mound of stone to top of post, for the  $\frac{1}{4}$  sec. cor. of sec. 2 only, with brass cap mkd.

 $\frac{1}{4}$  S 2

1935

QUARTER SECTION COR. ON N. BDY. OF SEC. 3

From the  $\frac{1}{4}$  sec. cor. of sec. 34, T. 45 N., R. 58 E., heretofore described; West, 5.675 chs. dist.

To a point midway bet. the closing cor. of secs. 2 and 3, and the closing cor. of secs. 3 and 4.

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for the  $\frac{1}{4}$  sec. cor., sec. 3 only, with brass cap mkd.

 $\frac{1}{4}$  S 3

1935