

Chains
10.00

Intersect the original NE. cor. of allotment No. 334, which is a redwood stake, 3 ins. sq., 12 ins. above the ground, firmly set, with markings almost obliterated. This cor. is identical with the SE. cor. of allotment No. 493 and S-NE 1/64 cor. of sec. 26. I therefore remonument this cor. as follows:

Set an iron post, 3 ft. long, 1 in. dia., 26 ins. in the ground, for the SE. and NE. cors. of allotment Nos. 493 and 334 respectively, with brass cap mkd.

493	T13N
334	R28E
	S26
	1922

From this cor.

N. 89° 55' W., on a true line, on S. bdy. of allotment No. 493, identical with the N. bdy. of allotment No. 334.

19.99 Intersect the SW. and NW. cors. of allotment Nos. 493 and 334 respectively, the place of beginning.

Survey of the Methodist Episcopal Church Allotment.
Allotment to "The Board of Home Missions and Church Extension of the Methodist Episcopal Church," Patent.

$S\frac{1}{2}NE\frac{1}{4}NW\frac{1}{4}NE\frac{1}{4}$ of sec. 35, T. 13 N., R. 28 E.

Note:

Preliminary to the survey of this Allotment, which is a part of the original Walker River Agency and School Reservation Allotment, which latter was surveyed and cors. established by an allotting Agent of the Indian Office; I made a partial subdivision survey as far as necessary of sec. 35, and found nearly all allotment cors. under the prior subdivision survey in substantial accord with the theoretical points determined by me. Further as these prior subdivision lines and corners have been locally recognized by adjoining property owners, as evidenced by their permanent fence lines, ditches, and other improvements which are tied to these corners I adopt same in