

RETRACEMENT OF THE BOUNDARIES OF SECTION 1, T. 31 N., R. 33 E.

CHAINS

- 39.48 The Std. cor. of secs. 35 and 36, as established by Deputy Surveyor H.B. Maxson in 1893, which is a quartzite stone, 15x10x4 ins., set in a mound of stone, with 5 grooves on W. face. No other marks discernible. From this cor., a mound of stone, with a wooden post, 2x4 ins. and 4 ft. long in center of mound with words "Section Corner" in blue pencil marks on one face bears N.48°E., 1.61 chs. distant. This monument is on a very steep, rocky N. slope and it is probable that the stone marked by Deputy Surveyor F.H. Criss in 1901 has rolled down the slope altho diligent search failed to reveal a marked stone.
-
- From the Std. cor. of secs. 35 and 36, N.87°24' W., on true line, along N. bdy. of Sec. 1, Over mountainous land thru dense undergrowth, desc. 60 ft. over W. slope.
- 2.90 Small ravine, course N.30°W., asc. 200 ft. over rocky NE. slope.
- 9.20 Spur, slopes NW., desc. 300 ft. over broken W. slope thru scattering juniper timber, to closing cor.
- 25.00 Slope changes to broken SW.
- 29.74 The closing cor. of secs. 1 and 2, hereinbefore described. Land, mountainous. Soil, rocky; 4th rate on slopes; gravelly, 3rd rate on bottom lands. Undergrowth, sagebrush, willow, service-berry. Scattering juniper.
-

RETRACEMENT OF THE EAST BDY. OF SECTION 12, T. 31 N., R. 33 E.

Random Line.

- From the cor. of secs. 1 and 12, as established by Deputy Surveyor H.B. Maxson in 1893, South, on retracement,
- 39.85 Fall 55 lks. E. of the point for the $\frac{1}{4}$ sec. cor. of