

Corrective Survey of a portion of the S. Bdy. of T. 44 N., R. 30 E. 11

Chains	the ground to bed rock, and 6 ins. in a mound of stone for cor. of secs. 2 and 3, T. 43 N., R. 30 E., with brass cap mkd. T44N R30E S34 S 3 S 2 T43N R30E 1921 and raise a mound of stone, 2 ft. base, 1½ ft. high, S. of cor. Land, the east ½ mile is nearly level, the west ½ mile varies from level to rough mountainous. Soil, of level land, is deep sandy gravel clay loam, dry and some alkali the remaining portion is shallow soil, of loose sandy gravel clay loam formation on granite and lava formation Undergrowth, sagebrush, grease wood and very little grass.
Dependent Resurvey of Subdivisions of T. 44 N., R. 30 E.	
Chains	From the cor. of secs. 1, 2, 35 and 36, on S. Bdy. heretofore described, N. 0° 11' W., on a true line, bet. secs. 35 and 36. Over nearly level land, through dense undergrowth. 6.60 Road, from Big Creek to Hot Springs, bears N. 6° W. and S. 6° E. 39.92 Intersect the original ¼ cor. of secs. 35 and 36, which is a willow stake, greatly decayed with marks obliterated, 2 ft. long, 2 ins. sq. firmly set in a small mound of earth, no signs of the old pits were found. I now reestablish this cor. at its original point as follows: Alongside old stake Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for ¼ sec. cor., with brass cap mkd. ¼ S35 S36 1921 dig pits, 18x18x12 ins., N. and S. of cor., 3 ft. dist. From this cor. the erroneously set ¼ cor. of secs. 35