

Establishment of the $\frac{1}{4}$ sec. corners on the north
bdy. of T. 25 N.; R. 47 E. on the Fifth Std. Parallel North.

Chains

The Std. corners herein referred to are described in

Book "A", T. 26 N., R. 47 E.

From the Std. cor. of Ts. 26 N., Rs. 46 and 47 E.

East, on true line,

- 2.44 Set an iron post, 3 ft. long, 1 in. diam., 24 ins. in
the ground, for the $\frac{1}{4}$ sec. cor. of sec. 6 only, with
brass cap mkd:

$\frac{1}{4}$ S 6
1922

from which,

A pinon pine, 6 ins. diam., bears S.20°E., 3 lks.

distant, mkd: $\frac{1}{4}$ S6 BT

A juniper, 10 ins. diam., bears S.54°W., 16 lks.

distant, mkd: $\frac{1}{4}$ S6 BT

East, from the Std. cor. of secs. 31 and 32,

- 2.32 At mid-point between the closing corners of secs. 4 and
5, and 5 and 6,

Set an iron post, 3 ft. long, 1 in. diam., 16 ins. in
the ground to solid rock and 20 ins. in a mound of
stone, 2 ft. base, for the $\frac{1}{4}$ sec. cor. of sec. 5 only,
with brass cap mkd:

$\frac{1}{4}$ S 5
1922

East, from the Std. cor. of secs. 32 and 33,

- 2.27 $\frac{1}{2}$ At mid-point between the closing corners of secs. 3 and
4, and 4 and 5,

Set an iron post, 3 ft. long, 1 in. diam., 19 ins. in
the ground to solid rock and in a mound of stone, for
the $\frac{1}{4}$ sec. cor. of sec. 4 only; with brass cap mkd:

$\frac{1}{4}$ S 4
1922

Raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$ ft. high, S. of
cor.

East, from the Std. cor. of secs. 33 and 34,

- 2.36 At mid-point between the closing corners of secs, 2 & 3,