

DEPENDENT

RESURVEY OF A PORTION OF THE SUBDIVISIONS OF T. 29 N., R. 54 E.

CHAINS

- 20.30 Spur, 40 ft. above draw, projects E., desc. abrupt N. slope.
- 24.00 Creek, 60 ft. below spur, 3 lks. wide, 2 ins. deep, course E., asc. S. slope.
- 25.80 Point of rocky spur, 40 ft. above creek, projects SE., desc. 20 ft. over rocky NE. slope.
- 30.00 Draw, drains SE., asc. very rocky SW. slope 210 ft.
- 40.13 The $\frac{1}{4}$ sec. cor. of secs. 4 and 5, which is an iron post, 1 in. diam., firmly set in a mound of stone, properly marked and witnessed. This cor. will hereafter refer to sec. 5 only. I efface marks pertaining to sec. 4.
- 41.40 On very rocky and steep SW. slope, 30 ft. above $\frac{1}{4}$ sec. cor., Set an iron post, 3 ft. long, 1 in. diam., 22 ins. in the ground to bedrock, and 12 ins. in a mound of stone, 3 ft. base, for $\frac{1}{4}$ sec. cor. of sec. 4 only, with brass cap mkd:
- $$\left| \frac{1}{4} S4 \right.$$
- 1921
- Continue ascent of steep SW. slope.
- 56.20 Rocky spur, 150 ft. above cor., projects SE., continue over broken E. slope.
- 76.50 Low spur, projects NE., desc. 40 ft. over N. slope.
- 81.70 Head of small draw, drains E., asc. 50 ft. over rocky SE. slope.
- 83.38 The closing cor. of secs. 4 and 5, which is an iron post, 2 ins. diam., firmly set in a mound of stone, properly marked and witnessed. I reset this post at the intersection with the south bdy. of sec. 33, T30N R54E.
- 84.42 Intersect the south bdy. of sec. 33, West, 26.62 chs. distant from the cor. of secs. 3 and 4, previously described.
- At point of intersection,
Reset iron post, 3 ft. long, 2 ins. diam., 8 ins. in the ground to bedrock, and 20 ins. in a mound of stone, 4 ft. base, for closing cor. of secs. 4 and 5, with brass cap mkd: