

SUBDIVISIONS T. 32 N., R. 29 E.

CHAINS

the ground, for  $\frac{1}{4}$  sec. cor., with brass cap marked



Raise a mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.

44.38

Dry wash, drains NE.

79.58

The cor. of secs. 5, 6, 7 and 8

Land, gently rolling. Soil, sandy with gravel.

Timber, none. Undergrowth, sage and shadscale.

LATITUDES, DEPARTURES AND CLOSING ERRORS.

Lines designated	True bearings	Dist-ances	Latitudes		Departures	
			N	S	E	W
			Chs	Chs	Chs	Chs
E. boundary	South	480.18		480.18		
S. boundary	S89°22'W	39.76		.44		39.76
	N88°29'W	40.87	1.08			40.86
	West	398.76				398.76
W. boundary	North	479.54	479.54			
N. boundary	N89°57'E	478.20	.39		478.20	
Convergency					.62	
			481.01	480.62	478.82	479.38
			480.62			478.82
	Error in latitude.....		.49			
	Error in departure.....		.56			

GENERAL DESCRIPTION

About 12 sections in the southwest portion of the township are mountainous in character, there being many rock ledges and slides. The remainder of the township is rolling to level. The only cultivated area is a narrow strip contiguous to Cow Creek in SE  $\frac{1}{4}$  sec. 31 and W  $\frac{1}{2}$  sec. 32, which is settled by L. E. Hanan. He has a productive garden, and hay fields with a total area of about 10 acres, all of which is subject to irrigation. There is good grazing in the higher portions of the township.

The soil in the lowlands is a sandy loam, while much of a rocky nature prevails in the upper regions. Considerable placer mining has been done in extreme NE. portion, but mineral in paying quantities has not been found.