

6 Retracement of a Portion of the E. Bdy. T. 24 N., R. 64 E.

Chains

The true course of this mile is therefore N. $0^{\circ} 36'$ W.,
and the length 81.87 chs.

From the original cor. of secs. 1, 6, 7 and 12,
North, along the E. Bdy. of sec. 1.

40.21 Fall 68 lks. W. of the original $\frac{1}{4}$ cor. of secs. 1 and 6,
which is a decayed cedar post, 2 ins. sq., $1\frac{1}{2}$ ft. long,
broken off at the surface of the ground, dimly mkd. $\frac{1}{4}$.
The original position of cor. being determined by the
charred remains found at this point. All other evidences
have disappeared..

The true course of this $\frac{1}{2}$ mile is therefore N. $0^{\circ} 58'$ E.,
and the length 40.22 chs.

From this original $\frac{1}{4}$ sec. cor., with continuous measure-
ment, North, along the E. Bdy. of sec. 1.

82.59 Fall 18 lks. E. of the reestablished cor. of Tps., 24
and 25 N., Rs. 64 and 65 E., which is a limestone,
4x5x8 ins., above the ground, firmly set and marked
as described by the surveyor general.

The true course of this $\frac{1}{2}$ mile is therefore N. $0^{\circ} 15'$ W.,
and the length, 42.38 chs.

Retracement of a portion of the E. Bdy. T. 25 N., R. 64 E.

From the reestablished cor. of Tps. 24 and 25 N., Rs. 64
and 65 E., I retrace
North, along the E. bdy. of sec. 36.

39.98 Fall 1 lk. E. of the original $\frac{1}{4}$ cor. of secs. 31 and 36,
which is a limestone, 8x8x5 ins., above the ground,
firmly set, mkd. and witnessed as described by the
surveyor general.

The true course of this $\frac{1}{2}$ mile is therefore N. $0^{\circ} 01'$ W.,
and the length 39.98 chs.

Dependent Resurvey of the W. Bdy. T. 24 N., R. 65 E.