

Retracement of Mineral Claims, T. 30 N., R. 28 E.

Chains 2.56	To cor. No. 4, Silver King Extension Lode and cor. No. 5, Franklin Fraction Lode
	Thence
	S. 63° 32' W., along line 4-5, Silver King Extension Lode
6.34	To cor. No. 5, Silver King Extension Lode
	Thence
	N. 7° 26' W., along line 5-6, Silver King Extension Lode
6.35	To cor. No. 6, Silver King Extension Lode
	Thence
	N. 52° 47' E., along line 6-7, Silver King Extension Lode
14.71	To cor. No. 7, Silver King Extension Lode
	Thence
	S. 7° 28' E., along line 7-1, Silver King Extension Lode
8.99	To cor. No. 1, Silver King Extension Lode and cor. No. 2, Franklin Fraction Lode

BOUNDARIES OF T. 30 N., R. 28 E.

Latitudes, departures and closing errors.

Lines designated	True bearings	Dist- ances chs	Latitudes		Departures	
			N	S	E	W
E. boundary	South	447.33 ✓	447.33			
S. boundary	West	477.54 ✓				477.54
W. boundary	North	447.51 ✓	447.51			
N. boundary	East	476.90 ✓			476.90	
Convergency					62 ✓	
			447.51	447.33	477.52	477.54
			447.33			477.52
Error in latitude.....			18 ✓			
Error in departure.....						02 ✓

GENERAL DESCRIPTION.

The greater part of the township is located in a chain of high rugged mountains. The southeast third of the township is situated on a rocky flat of lava formation. The mountainous sections of the township are very rough, with numerous outcroppings of granite. The ravines have, almost without exception, steep, rocky sides, and gravelly, boulder-strewn, narrow bottoms.