

General Description

found, although not of merchantable value, yet serving all purposes incidental to ranch life in the nearby valleys.

The predominant types of undergrowth are, sagebrush, buckbrush, service berry, and manzanita.

Much prospecting for mineral has been carried on for several years, without finding any extensive bodies of value. Small deposits of copper are in evidence in sections 15 and 16, but not in sufficient quantities to warrant developement in any large degree.

Many springs are found in the highlands, which are sufficient to supply water for cattle and sheep that range there during the greater portion of the year

There are no settlers within the township, which is unsuited to any kind of pursuit, except stockraising.

The nearest postoffice is Carlin, Nevada, a town on the mainline of the Southern Pacific Railroad, which is located about 35 miles from the west boundary of the township.

Latitudes, Departures, and Closing Errors.

Line designated	Bearing	Distances	Latitudes		Departures	
			N	S	E	W
		Chs	Chs	Chs	Chs	Chs
E. boundary	South	478.92		478.92		
S. boundary	N89°55'W	484.95	.70			484.95
W. boundary	North	40.10	40.10			
	NO°11'E	79.89	79.89		.26	
	NO°07'E	39.99	39.99		.08	
	NO°02'W	39.95	39.95			.02
	NO°02'E	40.00	40.00		.02	
	NO°03'W	39.93	39.93			.03
	NO°01'W	40.06	40.06			.01
	NO°04'E	40.20	40.20		.05	
	NO°09'E	79.80	79.80		.21	
	NO°08'E	38.47	38.47		.09	
N. boundary	S89°54'E	40.07		.07	40.07	
	S89°53'E	39.88		.08	39.88	
	S89°57'E	39.82		.03	39.82	
	S89°47'E	40.04		.15	40.04	
	N89°53'E	39.46	.08		39.46	
	East	284.81			284.81	
	Convergency				.61	
			479.17	479.25	485.40	485.01
				479.17	485.01	
Error in latitude.....			.08			
Error in departure.....			.39			