

Subdivisions, T. 28 N., R. 54 E.

Chains 64.70	Draw, drains S. Asc. SE. slope 70 ft. to
74.00	Spur, projects S. Desc. W. slope 90 ft. to
79.50	Draw, drains S. Asc. gentle E. slope
79.98	The cor. of secs. 5, 6, 7 and 8 Land, rolling mountainous. Soil, rocky. Timber, none. Undergrowth, sagebrush. General drainage, S. Grazing, poor.
24.83	S. 89° 57' W., on a random line bet. frac. secs. 6 and 7 Intersect the cor. of secs. 1, 6, 7 and 12, on W. bdy. of twp, which is described in the field notes of the survey of T. 28 N., R. 53 E., under Group No. 111, and made in conjunction with the survey of this township Thence N. 89° 57' E., on true line bet. frac. secs. 6 and 7 Over rolling land. Desc. W. slope 50 ft. to 9.10 Ravine, drains SE. Asc. SW. slope 35 ft. to 19.55 Spur, projects S. Desc. SE. slope 35 ft. to 24.83 The cor. of secs. 5, 6, 7 and 8 Land, rolling. Soil, gravelly clay. Timber, none. Undergrowth, sagebrush. General drainage, SE. Grazing, poor.
40.00	N. 0° 10' W., on a random line bet. secs. 5 and 6 Set temp. $\frac{1}{4}$ sec. cor.
78.84	Intersect N. bdy of twp. 14 lks. W. of the cor. of secs. 31 and 32, which is a 2 in. iron post, properly set, mkd. and witnessed, as described in the field notes of the survey of T. 29 N., R. 54 E., under Group No. 94, I change markings to read as follows: <div style="text-align: center;"> T29NR54E S31 S32 ———— S6 S5 T28N 1926 </div> Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor. Thence S. 0° 04' E., on true line bet. secs. 5 and 6