			- (4)				
Boundaries	of.	T.	23	N	R.	49 E	

Latitudes, departures and closing errors.

- 1						
The second second		True :				P255
	The same and the		Chs.	Chs. C	hs. Chs.	Chs.
	S.bdy.T23 N R49E	West	479.54			479.54
	W. " " "	North /	,81.61/	81.61/.		_
The state of the state of	S.hdy.T24N R48 E.	East	78.18		78.3	18/ .
	S.bdy. T24N R49E	East / .	318.19		318.3	19/ .
	s. " " ". s	.89°30'E .	79.90 /		.70 79.9	30 · .
	s. " " s	.89°30!E .	2.99		.03 2.9	997.
	E.bdy.T232N R49E	South .	80.55 %	. 8	0.55	
	Convergency			" T I		10,
	Totals				1.28 479.3	1
	Errors in lat.	and den.		0.33		0.18

GENERAL DESCRIPTION OF T. 23 N., R. 49 E.

The lands embraced within this fractional township is mainly rolling mountainous or rolling. The eastern portion has a general northeasterly and northerly exposure and drainage into Tonkin Creek, which drains towards Denay Valley. The central portion comprising of the major portions of secs. 4 and 5, has a southerly exposure and drainage towards Coils Creek; and and western portion faces N. to NW. and drains into Antelope Creek. The eastern part of township is covered with a scattering growth of scrub cedar and pinon pine timber, while the west portion is nearly void of timber. Dense black sagebrush from 1 to 3 ft. high is found throughout the township.

The soil is principally a dry, firm gravelly to gravelly

clay, lying on subsoil of cemented gravel or stiff clay,