

West Boundary of T. 27 N., R. 40 E.

Chains	Set an iron post, 3 ft. long, 1 in. dia., 10 ins. in the ground to solid rock, in a mound of stone, for the sec. cor. of sec. 1 only, with brass cap mkd
	S 7 1929
42.00	At base of post deposit a mkd(X)basalt stone, 5x5x6 ins.
51.40	Draw, drains S. 45° E. about 10 chs., thence S.
	Asc. general SW. slope 130 ft. to sec. cor. at 80.00
56.92	Set an iron post, 3 ft. long, 2 ins. dia., 10 ins. in the ground to solid rock, in a mound of stone, for the cor. of secs. 1 and 12 only, with brass cap mkd
	R39E R40E S1 S7 S12 T27N 1929
61.20	Thence over rolling bench land to sec. cor. of sec. 12
80.00	Set an iron post, 3 ft. long, 2 ins. dia., 27 ins. in the ground; for the cor. of secs. 6 and 7 only, with brass cap mkd
	R39E R40E S1 S6 S7 T27N 1929
12.00	Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, E. of cor.
16.80	Land, rolling mountainous. Soil, sandy gravelly loam, 3rd rate. Timber, none. Undergrowth, sage, shadscale.
16.92	General drainage, SE. Grazing, poor.
12.00	Asc. general SE. slope 35 ft. to 25.65
16.80	Draw, drains S. 40° E.
16.92	Set an iron post, 3 ft. long, 1 in. dia., 20 ins. in the ground to solid rock, in a mound of stone, for the sec. cor. of sec. 1 only, with brass cap mkd

S 7
1929