

ESTABLISHMENT OF QUARTER-SECTION
 CORNERS BETWEEN CLOSING CORNERS WEST BOUNDARY OF
 T.22 S., R.63 $\frac{1}{2}$ E.

Chains

From the cor. of secs. 1 and 12, E. bdy. of T.22 S., R.63 $\frac{1}{2}$ E., which is an iron post, 2 ins. in diam., firmly set, and marked and witnessed as described in the official record, Book "B", this group.

N.0°11'E., along E. bdy. sec. 1, T.22 S., R.63 E.

10.59 Mid-point bet. the closing cor. of secs. 12 and 13 and the closing cor. of secs. 1 and 12, T.22 S., R.63 $\frac{1}{2}$ E.

Set an iron post, 3 ft. long, 1 in. in dia., 28 ins. in the ground for $\frac{1}{4}$ sec. cor. W. bdy. sec. 12, T.22 S., R.63 $\frac{1}{2}$ E., with brass cap marked

$\frac{1}{4}$
S12

1931

raise a mound of stone, 3 ft. base, 2 ft. high, E. of cor.

From the cor. of Tps. 21 and 22 S., R.63 E., which is an iron post, 3 ins. in dia., firmly set alongside the original cor. monument, and marked and witnessed as described in the official record, Book "B", this group.

N.2°27'E., along E. bdy. sec. 36, T.21 S., R.63 E.

6.10 $\frac{1}{2}$ Northing of 40.00 chs. from the closing cor., of secs. 1 and 12, W. bdy. of T.22 S., R.63 $\frac{1}{2}$ E.

Set an iron post, 3 ft. long, 1 in. in dia., 30 ins. in a large mound of stone over a cross (+) cut in solid rock for $\frac{1}{4}$ sec. cor. W. bdy. sec. 1, T.22 S., R.63 $\frac{1}{2}$ E., with brass cap marked

$\frac{1}{4}$
S1

1931

Cor. stands in the head of a small draw draining NW.

GENERAL DESCRIPTION

The lands in this fractional township are rough and broken mountainous with a general west drainage. There are no prominent topographic features.

The soil is a very shallow rocky clay loam with many large surface rocks and boulders; the lands have little or no value for agricultural purposes. There is no water.

No settlers reside in the township. An old road and the recently constructed telephone line, Las Vegas to Boulder City, run northwesterly thru a portion of sec. 25.

The magnetic declination was not recorded. There are numerous mineral prospect holes but no indication of mineral in commercial quantities was observed.