

## SUBDIVISION OF T. 11 N., R. 30 E.

## Chains

Land, mountainous.  
Soil, shallow rocky loam, 3rd and 4th rate.  
Undergrowth, shadscale, greasewood.  
No timber.  
Grazing, fair to poor.

West, on true line bet. secs. 19 and 30.

Over mountainous land thru scattering low undergrowth.  
Desc. 100 ft. over NW. slope.

8.20 Draw, drains S. 55° W., asc. along SE. slope.

15.80 Spur, slopes S. 30° E., desc. 120 ft. over SW. slope.

22.00 Recross same draw, drains N. 60° W. from SE.

26.80 Same draw, drains S. 50° W.

29.70 Same draw, drains N. 60° W., asc. 80 ft. over NE. slope.

34.30 Spur, slopes N. 70° W., desc. 60 ft. over rocky SW. slope.

40.00 True point for  $\frac{1}{4}$  sec. cor., falls on sloping surface rock where it is unsafe to establish corner monument.

Therefore, at

40.60 Set an iron post, 3 ft. long, 1 in. diam., 8 ins. in the ground over a cross X, cut at exact cor. point on solid rock, and in a large mound of stone to top of post, for witness  $\frac{1}{4}$  sec. cor., with brass cap mkd.

S 19  
—  $\frac{1}{4}$  — WC ✓  
S 30

Desc. 100 ft. over rocky SW. slope.

48.10 Draw, drains N. 65° W., continue along a rocky NE. slope.

73.00 Spur, slopes N. 80° W. from S. 60° E., desc. along rocky S. slope.

80.00 Set an iron post, 3 ft. long, 1 in. diam., 20 ins. in the ground to underlying rock, and in a large mound of stone to top of post, for cor. of lots 7 and 8 in Sec. 19 and lots 1 and 2 in Sec. 30, with brass cap mkd.

S 19  
7 — 8 ✓  
2 — 1  
S 30  
1938

Desc. 70 ft. over SW. slope.

86.20 Draw, drains N. 60° W., asc. along N. slope.

91.90 End of spur from S., desc. 70 ft. over NW. slope.

101.00 Intersect W. bdy. of Tp.

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for closing cor. of secs. 19 and 30, with brass cap mkd.