

Independent Resurvey, Portion of the South Boundary, T. 20 N., R. 52 E.

Chains

Superseding the Survey Executed by  
E. B. Monroe, Deputy Surveyor, in 1884.

Beginning at the cor. of Ts. 19 and 20 N., Rs. 52 and 53 E., which was reestablished by double proportionate measurement, under Group 133, Nevada, in 1933, and is monumented with an iron post, 3 ins. diam., firmly set, mkd. and witnessed as described in the official record. As this corner will no longer serve for Ts. 19 N., Rs. 52 and 53 E., I alter the markings on the brass cap so that it now reads:

T20N  
R52E R53E  
S36|S31  
S 6  
T19N R53E  
1937  
1933

From this corner, the original  $\frac{1}{4}$  sec. cor. of secs. 1 and 6, Ts. 19 N., Rs. 52 and 53 E., which is monumented with a granite stone, 14x12x10 ins., firmly set and mkd. as described in the official record, bears S. 11° 04' E., 40.29 chs. dist. As this corner will no longer serve as a  $\frac{1}{4}$  sec. cor., I destroy it and its accessories.

Thence, from the cor. of Ts. 20 N., Rs. 52 and 53 E.

West, along the S. bdy. of sec. 36, T. 20 N., R. 52 E.

Over rough mountainous land, through scattering scrubby timber and medium dense undergrowth; asc. 310 ft. over abrupt E. slope.

14.80 Spur, slopes N. 80° E. from W.; asc. along crest of same.

19.20 Spurs, slope E. and N. 10° W., from S.; desc. 180 ft. over W. slope, changing in advance to SW.

27.65 Point for the closing cor. of Ts. 19 N., Rs. 52 and 53 E., hereinafter described.

40.00 Point for the S.  $\frac{1}{4}$  sec. cor. of sec. 36; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 4 ins. in the ground, over an "X" chiseled on solid rock, and in a mound of stone, 4 ft. base, 32 ins. high, with brass cap mkd.

$\frac{1}{4}$  S 36  
1937

No auxiliary accessory.

This corner is situated on crest of a spur, slopes SW.

Thence along S. slope.

42.25 Change to SW. slope; desc. 220 ft. over same to drain.

60.00 Drain, course N. 60° W.; thence along broken N. slope.