

RESURVEY OF THE S. BDY. of T. 23 $\frac{1}{2}$ S., R. 64 E.

Chains

79.70

Road bears N. 22° E. and S. 22° W.

80.00

The cor. of secs. 3, 4, 33 and 34, an iron post, 2 ins. diam., set, mkd. and witnessed as described in the official record. I alter the markings to refer to secs. 33 and 34 only, to read as follows:

T23 $\frac{1}{2}$ S	R64E
S33	S34
S4	
T24S	R64E
1931	

Reconstruct mound
of stone around post.

N. 89° 29' W., along S. bdy. of sec. 33.

0.60

Center line of power line, bears N. 22° 02' E. to Boulder Dam and S. 22° 02' W.

40.00

The $\frac{1}{4}$ sec. cor., an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record. I alter the markings to refer to sec. 33 only to read as follows:

$\frac{1}{4}$ S 33
1931

80.00

The cor. of secs. 4, 5, 32 and 33, an iron post, 2 in. diam., set, mkd. and witnessed as described in the official record. I alter the markings to refer to secs. 32 and 33 only to read as follows:

T23 $\frac{1}{2}$ S	R64E
S32	S33
S5	
T24S	R64E
1931	

reconstruct mound
of stone, 2 ft. base, 1 $\frac{1}{2}$ ft. high, N. of cor.

N. 89° 29' W., along S. bdy. sec. 32.

22.70

Wooden pole telephone line bears N. 22° E. and S. 22° W.

40.00

The $\frac{1}{4}$ sec. cor., an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record. I alter the markings to refer to sec. 32 only to read as follows:

$\frac{1}{4}$ S 32
1931

80.00

The cor. of secs. 5, 6, 31, and 32, an iron post, 2 ins. diam., set, mkd. and witnessed as described in the official record. I alter the markings to refer to secs. 31 and 32 only to read as follows:

T23 $\frac{1}{2}$ S	R64E
S31	S32
S6	
T24S	R64E
1931	

reconstruct mound
of stone, 2 ft. base, 1 $\frac{1}{2}$ ft. high, N. of cor.

N. 89° 29' W. along S. bdy. sec. 31.