

Dependent Resurvey of a Portion of the Fourth Standard Parallel South
through R. 67 E.

- 40.29 Point for the standard $\frac{1}{4}$ sec. cor. of sec. 36, at proportionate dist.; there is no remaining evidence of the original cor.
- At the cor. point.
- Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground, in a collar of stone, with brass cap mkd.
- T16S R67E
S C
 $\frac{1}{4}$ S36
1959
- Cont, over rolling land with NE drainage.
- 69.60 NW edge of rolling land; desc. 50 ft. over NW facing bank.
- 74.90 Improved road, bears NE. and SW.
- 80.58 True point for the standard sec. cor. of secs. 35 and 36, at proportionate dist.; there is no remaining evidence of the original cor. The true point falls in wash, 2.00 chs. wide, 2 ft. deep, draining NE. where the monument cannot be perpetuated.
- Land, rolling.
Soil, rocky and sandy silt.
Timber, none.
Undergrowth, creosote bush, mountain rush and cacti.
-
- N. $89^{\circ} 59'$ W., along the S. bdy. of sec. 35.
- Over rolling land; asc. 70 ft. over steep SE. facing bank.
- 1.30 Point selected for the witness standard sec. cor. of secs. 35 and 36.
- At the point for the witness cor.
- Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
- T16S R67E
S C
S35|S36 W
1958 C
- Thence over series of washes draining SE.
- 20.00 Drainage changes to NE.; cont. over series of washes.
- 40.29 Point for the standard $\frac{1}{4}$ sec. cor. of sec. 35, at proportionate dist.; there is no remaining evidence of the original cor.
- At the cor. point
- Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground, in a collar of stone, with brass cap mkd.
- T16S R67E
S C
 $\frac{1}{4}$ S35
1959
- Cont. over series of NE. draining washes.