

## Dependent Resurvey of the South Boundary, T. 24 N., R. 41 E.

Chains	
5.60	Trail road, bears N. and S.
9.30	Bulldozed road, bears N. 80° E. and S. 80° W.
11.20	Wash, 20 lks. wide, 4 ft. deep, drains N.
33.70	Small wash, drains N. 30° W.
39.68	Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 31, at proportionate dist.; there is no remaining evidence of the original cor.  Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.  T24N R41E $\frac{1}{4}$ $\frac{S31}{S6}$ T23N 1960  No available accessories.
77.58	The cor. of Tps. 23 and 24 N., Rs. 40 and 41 E., monumented with an iron post, 2½ ins. diam., conforming to the field notes of the concurrent resurvey of T. 24 N., R. 40 E.  Land, nearly level. Soil, light sandy clay. Timber, none. Undergrowth, shadscale.

Dependent Resurvey of the Subdivisional Lines of  
T. 24 N., R. 41 E.

Reestablishment of the survey of the subdivisional lines executed by Deputy Surveyors D. H. Barker and J. H. Eaton in 1876.

The point for cor. of secs. 1, 2, 11 and 12, is determined at record dist. from the N. and W. boundaries of the Tp.; there is no remaining evidence of the original cor.

At the cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T24N R41E  
S2|S1  
S11|S12  
1960

No available accessories.

N. 2° 43' E., bet. secs. 1 and 2.

Over rolling land.

12.60	Small wash, drains W.
24.60	Bulldozed road, bears N. 60° W. and S. 40° E.
26.60	Small wash, drains S. 80° W.; asc. 30 ft. over S. slope.
36.40	Small spur, slopes W.; desc. 10 ft. over NW. slope.
40.04	Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 2, at record dist.; there is no remaining evidence of the original cor.