

Dependent Resurvey of the Subdivisional Lines, T. 10 N., R. 43 E.

Chains

From this corner, the standard $\frac{1}{4}$ sec. cor. of sec. 32, T. 11 N., R. 43 E., monumented with an iron post, $2\frac{1}{2}$ ins. diam., hereinbefore described bears S. $89^{\circ} 57' E.$, 2.83 chs. dist.

From this same corner, the standard corner of secs. 31 and 32, T. 11 N., R. 43 E., monumented with an iron post, $2\frac{1}{2}$ ins. diam. hereinbefore described, bears N. $89^{\circ} 57' W.$

The point for the N. $\frac{1}{4}$ sec. cor. of sec. 6 on the N bdy. of the Tp. is at proportionate distance as based upon the original plat.

At the corner point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T11N R43E

$\frac{1}{4}$ S 6
T10N R43E
1961

Raise a mound of stone, $3\frac{1}{2}$ ft. base, $2\frac{1}{2}$ ft. high, S. of corner.

From this corner, the standard $\frac{1}{4}$ sec. cor. of sec. 31, T. 11 N., R. 43 E., monumented with an iron post, $2\frac{1}{2}$ ins. diam., hereinbefore described bears S. $89^{\circ} 57' E.$, 2.64 chs. dist.

From this same corner, the corner of Ts. 10 and 11 N., Rs. 42 and 43 E., monumented with an iron post, $2\frac{1}{2}$ ins. diam., hereinbefore described, bears N. $89^{\circ} 57' W.$

 General Description

Township 10 North, Range 43 East, is located in a large valley known as Smoky Valley, and lies between the Toiyabe and Toquima Mountain Ranges.

The land for the most part is nearly level to gently rolling and western half of sections 6, 7, 18 and a portion of 19, is rough, broken mountainous land, with some scattering timber.

The soil in the township is a sandy and gravelly clay loam, and there is a fair growth of native grasses along the main water courses. There is a small creek in the northern part of sec. 12, and Jefferson Creek is in the central part of Sec. 1, both flowing in a westerly direction. Summit creek is located in sec. 18 and flows in a north-easterly direction. These creeks only flow intermittently during the year.

There is one rancher located in sec. 4 in the township, who has developed water and has a small area cleared and seeded to pasture, but predominating use of the land is for stock grazing.

Highway No. 8-A., an oil surfaced road, enters the township from the south near the $\frac{1}{4}$ sec. cor. of secs. 3 and 34, on the S. bdy., traverses in a general NE. direction through sections 34, 35, 26, 23, and 14, thence in a general NW. direction through sections 11, 10, and 3, and leaves the township near the corner of secs. 3 and 4, on the N. bdy. of the township.

There is one mill site, not in use at this time, for the processing of ores for the production of gold and copper located in the NE $\frac{1}{4}$ SE $\frac{1}{4}$ of sec. 24.