UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FIELD NOTE PAPER CHAINS 38.90 Deep Creek, 20 lks. wide, 4 ft. deep, drains W. 39.39 Point for the 4 sec. cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground and in a collar of stone, with brass cap mkd. $S \quad 2 \mid S$ Asc. 70 ft. over SE. slope. 59.00 Spur, bears SW.; continue along W. slope. 67.10 Wash, 10 1ks. wide, 2 ft. deep, drains W.; asc. 40 ft. over SE. slope. 79.19 The cor. of secs. 1, 2, 35 and 36 on the N. bdy. Land, rolling. Soil, sandy clay. Undergrowth, sagebrush, shadscale and buttonbrush. From the cor. of secs. 2, 3, 34 and 35 on the S. bdy. of the Tp., an iron post, $2\frac{1}{2}$ ins. diam., set, mkd., and witnessed as described in the field notes of the concurrent resurvey of T. 43 N., R. 31 E. N. 1° 26' E., bet. secs. 34 and 35. Over nearly level land, through medium undergrowth. 38.26 Point for the 1/2 sec. cor. of secs. 34 and 35, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground and in a collar of stone, with brass cap mkd. T44N R31E S 34 | S 35 1962 The cor. of secs. 26, 27, 34 and 35, monumented with 76.52 the remains of the original wood post. At the corner point Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground and in a collar of stone, with brass cap mkd. T44N R31E S 27 S 26 S 34 S 35 1962

Reset the original wood post alongside the iron post.