

Chains


35.00

Asc. 130 ft. over steep S. slope.

40.40

Proportionate distance.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.



raise a mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.

Asc. 50 ft. over S. slope.

43.00

Spur, slopes W.; desc. 80 ft. over NW. slope.

46.20

Wash, course SW.

52.10

Wash, course SW.; asc. 1000 ft. over steep broken S. to SE. slope.

76.70


Top of mountain, bears S.  $20^\circ$  W. and N.  $20^\circ$  E.; desc. 60 ft. along rough broken W. slope.

80.80

Proportionate distance.

Chisel a cross (X) on W. face of ledge at point for corner, and at a point on line bet. secs. 1 and 12, N.  $88^\circ 45'$  W., 0.10 chs. dist.

Set an iron post, 3 ft. long, 2 ins. diam., in a mound of stone to top, with a stone  $12 \times 4 \times 3$  ins., mkd. X deposited at base, for wit. cor. of secs. 1, 6, 7 and 12, with brass cap mkd.



from which,

A cross (X) and the letters BO, chiseled on face of ledge, bear S.  $15^\circ$  E., 28 lks. dist.

Land, rolling and rough broken mountainous.

Soil, rocky, 4th rate.

Timber, none.

Undergrowth, sagebrush.

Grazing, fair.

N.  $1^\circ 07'$  W., bet. secs. 1 and 6.

Desc. 50 ft. along W. slope.


14.00

Desc. 700 ft. over NW. slope.

40.40

Proportionate distance.

Set an iron post, 3 ft. long, 1 ins. diam., 27 ins. in the ground, with a granite stone  $5 \times 3 \times 3$  ins., mkd. X, deposited at base, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.



Desc. 250 ft. over NW. slope.