

Dependent Resurvey of the South Boundary of  
T. 34 N., R. 62 E.

## Chains

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with glass, and the original stake deposited at base, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$   $\frac{S33}{S4}$   
1942

No suitable accessory.

Thence

N. 88° 40' E., bet. secs. 4 and 33. (E.  $\frac{1}{2}$  mile.)

Over level land.

34.05 The original meander cor. of secs. 4 and 33, a juniper post, 40 ins. long, 2 ins. diam., squared at top, decayed no legible markings.

At point for corner

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground with a bottle and the original post deposited at base, for meander cor. of secs. 4 and 33, with brass cap mkd.

T34N  
S33  
R62E ——— MC  
S4  
T33N  
1942

No suitable accessory.

Land, level.

Soil, sandy clay; 3rd rate.

No timber.

Undergrowth, sagebrush, greasewood, shadscale and salt grass.

Grazing, poor.

Dependent Resurvey of the East Boundary of  
T. 34 N., R. 62 E.

Reestablishment of surveys executed by  
Hatch and Eaton, Deputy Surveyors in  
1870.

From the cor. of Tps. 34 and 35 N., Rs. 62 and 63 E.

S. 0° 11' W., bet. secs. 1 and 6.

Over nearly level land.

0.20 Very dim road, bears E. and W.

22.90 Road, bears E., W. and S.

39.98 Proportionate point, on W. side of road, bears N. and S.