

DEPENDENT RESURVEY OF A PORTION OF THE WEST BOUNDARY,
T. 32 N., R. 45 E.

CHAINS

DEPENDENT RESURVEY OF A PORTION OF THE WEST BOUNDARY OF
T. 32 N., R. 45 E., MOUNT DIABLO MERIDIAN, NEVADA

Reestablishment of the Survey Executed by
Hatch and Eaton, U. S. Deputy Surveyors, in 1869
and of the Resurvey Executed by
A. T. Harris, U. S. Transitman, in 1914.

N. 0° 32' W., along the W. bdy. of sec. 31.

Over nearly level land, through medium undergrowth.

34.16 The $\frac{1}{4}$ sec. cor. of sec. 36 only, T. 32 N., R. 44 E., monumented with an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record. All markings were removed in 1966 and the brass cap was remarked AM, 1966, 1914. In May 1971 this iron post was found rusted off.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.

T32N
R44E R45E
 $\frac{1}{4}$
S 36

1971
1914

reset the remains of the 1914 iron post alongside the iron post and raise a mound of stone, 3 ft. base, $2\frac{1}{2}$ ft. high, W. of cor.

40.11 The $\frac{1}{4}$ sec. cor. of sec. 31 only, T. 32 N., R. 45 E., monumented with an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record. The brass cap is remarked to read as follows:

T32N
R44E R45E
 $\frac{1}{4}$
S 31

1971
1914

Note: The brass cap had been remarked as the $\frac{1}{4}$ sec. cor. of secs. 31 and 36 in 1966 and the marks T. 32 N., R. 44 E.-R. 45 E., S 36 1966 were added.

raise a mound of stone, 3 ft. base, 2 ft. high, E. of cor

N. 0° 32' W., beginning new measurement.

Over nearly level land.

23.50 Trail road, bears NE. and SW.

24.70 Trail road, bears NE. and SW.

31.10 Trail road, bears NE. and SW.

33.00 Trail road, bears NE. and SW.