

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
T. 32 N., R. 45 E.

CHAINS	
78.20	Trail road, bears N. and S.
78.54	<p>The cor. of secs. 19 and 30, on the W. bdy. of the Tp.</p> <p>Land, level. Soil, sandy loam and alkali. Undergrowth, greasewood.</p>
<p><b>GENERAL DESCRIPTION</b></p> <p>The land within secs. 30 and 31, T. 32 N., R. 45 E. is nearly level and the elevation is about 4,500 ft. above sea level. The soil is sandy loam, gravel and alkali. The vegetation consists of greasewood, sagebrush, shade scale and sparse native grasses.</p> <p>No mineral formations of consequence were noted during the survey.</p> <p>Principal users of the area are cattlemen and access into the township is provided by desert roads. The cor. of secs. 29, 30, 31 and 32, falls in the junkyard of the town of Battle Mountain.</p>	