

DEPENDENT RESURVEY AND COMPLETION SURVEY,  
T. 23 N., R. 18 E., MDM, NEVADA

CHAINS

Point for the S.  $\frac{1}{4}$  sec. cor. of sec. 32, is on the N. bdy. of sec. 5, T. 22 N., R. 18 E., at midpoint and on the S. bdy. of sec. 32.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 10 ins. in the ground to solid rock and in a mound of stone, 4 ft. base to cap, with brass cap mkd.

T23N R18E  
 $\frac{1}{4}$  S 32

1972

From this cor., the  $\frac{1}{4}$  sec. cor. of sec. 5, T. 22 N., R. 18 E., bears N.  $89^{\circ} 24'$  E., 2.79 chs. dist.

GENERAL DESCRIPTION

The area surveyed and resurveyed within Township 23 North, Range 18 East, varies from mountainous in the west portion to nearly level in the central portion with the remaining terrain being gently rolling. The elevation ranges from about 4,700 to 7,100 ft. above sea level. The soil varies from sandy clay loam in the level portion and rocky on the higher elevations. The vegetation consists of sagebrush, bunchgrass, desert peach and mountain mahogany in the higher elevations.

Red Rock Road crosses the Township in a northwesterly direction. Red Rock Ranch is located in secs. 23 and 26. Rancho Haven is located in sec. 22. There are numerous springs throughout the Township. No mineral formations of consequence were noted during the survey.