

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
T. 35 N., R. 39 E.

## CHAINS

From this same corner, the standard  $\frac{1}{4}$  sec. cor. of sec. 35, T. 36 N., R. 39 E., monumented with an iron post,  $2\frac{1}{2}$  ins. diam., set, mkd. and witnessed as described in the official record, bears WEST, 27.46 chs. dist.

The point for the  $\frac{1}{4}$  sec. cor. on the N. bdy. of sec. 1, is on the S. bdy. of T. 36 N., R. 39 E. and at midpoint on the N. bdy. of sec. 1.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

T36N R39E

$\frac{1}{4}$  S 1  
T35N R39E

1971

set a steel fence post,  $5\frac{1}{2}$  ft. long,  $2\frac{1}{2}$  ft. in the ground, alongside the iron post.

From this corner, the standard  $\frac{1}{4}$  sec. cor. of sec. 36, T. 36 N., R. 39 E., monumented with an iron post,  $2\frac{1}{2}$  ins. diam., set, mkd. and witnessed as described in the official record, bears N.  $89^{\circ} 52' E.$ , 13.33 chs. dist.

From this same corner, the standard cor. of secs. 35 and 36, T. 36 N., R. 39 E., monumented with an iron post,  $2\frac{1}{2}$  ins. diam., set, mkd. and witnessed as described in the official record, bears S.  $89^{\circ} 52' W.$ , 26.79 chs. dist.

From the cor. of secs. 25, 26, 35 and 36.

S.  $87^{\circ} 42' W.$ , bet. secs. 26 and 35.

Over mountainous land, through medium undergrowth; asc. 50 ft. over E. slope.

10.30 Trail road, bears SE. and NW.; asc. 60 ft. over E. slope.

18.00 Slope changes; asc. 100 ft. along N. slope.

40.75 Point for the  $\frac{1}{4}$  sec. cor. of secs. 26 and 35, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 16 ins. in the ground to solid rock and in a collar of stone, with brass cap mkd.

T35N R39E  
 $\frac{1}{4}$  S 26  
S 35

1971