


DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
T. 2 N., R. 42 E., MDM, NEVADA

<div>CHAINS</div> <div>40.17</div>	<div><p>Cor. No. 8 of M.S. 4469, Taft lode, monu- mented with the remains of a pine post in a mound of stone, bears N. 11° 20' W., 5.19 chs. dist.</p><p>At the corner point</p><p>Set an iron pipe, 1 in. diam., in a drill hole, with brass tablet secured to the top and mkd.</p><div></div><p>raise a mound of stone, 4 ft. base, 3 ft. high, SE. of cor.</p><p>Ascend 20 ft. over W. slope.</p><p>The cor. of secs. 2, 3, 34 and 35, on the N. bdy. of the Tp.</p><hr/><p>DEPENDENT RESURVEY AND RETRACEMENT OF A PORTION OF MINERAL SURVEY NO. 4262, T. 2 N., R. 42 E., MOUNT DIABLO MERIDIAN, NEVADA</p><hr/><p>Reestablishment of a Portion of Mineral Survey No. 4262, Executed by Warren V. Richardson, U. S. Mineral Surveyor, in 1915.</p><hr/><p>BANNER LODGE</p><p>Cor. No. 1 of M.S. 4262, Banner lode, identical with Cor. No. 4 of M.S. 4262, Roosevelt lode, determined at record bearing and distance from the cor. of secs. 1, 2, 35 and 36; falls near the center of U. S. Highway No. 95:</p><p>from which</p><p>The cor. of secs. 1, 2, 35 and 36, heretofore described, bears N. 15° 51' 40" W., 12.947 chs. dist.</p><p>At the corner point</p><p>Set a copper-coated steel stake, 24 ins. long, ½ in. diam., flush with pavement, with brass cap mkd.</p></div>
------------------------------------	---