

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
T. 23 N., R. 53 E., MDM, NEVADA

CHAINS	
39.00	Spring branch, course NE.
40.29	Point for the $\frac{1}{4}$ sec. cor. of secs. 18 and 19, at proportionate distance; there is no remaining evidence of the original corner.  Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.  <div style="text-align: center;"> T23N R53E  <math>\frac{1}{4}</math> <math>\frac{S\ 18}{S\ 19}</math>  1972 </div> raise a mound of stone, 3 ft. base, 2 ft. high, N. of cor.
57.20	Fence, bears SE. and NW.
60.30	Trail road, bears SE. and NW.
60.90	Fence, bears SE. and NW.
79.06	The cor. of secs. 13, 18, 19 and 24, on the W. bdy. of the Tp., monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set and exposed 6 ins. above ground, with a mound of stone, 3 ft. base, 2 ft. high, W. of cor., with brass cap mkd. as described in the field notes of the resurvey of the E. bdy. of T. 23 N., R. 52 E., executed concurrently under this same group.
	<div style="text-align: center;">GENERAL DESCRIPTION</div> <p>The area resurveyed in Township 23 North, Range 53 East, is nearly level and about 5,800 ft. above sea level. The soil is sandy clay. The vegetation consists of sagebrush and greasewood. Seep springs are located in section 19. The principal users of the area are cattlemen.</p> <p>No mineral formation of consequence was noted.</p> <p>Access in the area is provided by a graded road and a few trail roads.</p>