

Dependent Resurvey of the N. Bdy.,
T. 32 N., R. 32 E., M.D.M., Nevada

CHAINS
40.55

Point for the 1/4 sec. cor. of secs. 6 and 31,
at proportionate distance; there is no remaining
evidence of the original cor.

Set an iron post, 28 ins. long, 2-1/2 ins. diam.,
22 ins. in the ground, with brass cap mkd.

T 33 N R 32 E
1/4 S 31
S 6
T 32 N
1974

Set a steel fence post, 5-1/2 ft. long, alongside
the iron post.

78.00

Ravine, drains N. 80° E.

79.10

The cor. of Tps. 32 and 33 N., Rs. 31 and 32 E.,
monumented with an iron post, 3 ins. diam.,
firmly set and exposed 14 ins. above the ground,
with brass cap mkd.

R31E T 33 N
S 36 | S 31
S 1 | S 6 R32E
T 32 N
1912

Rebuild mound of stone, 5 ft. base, to cap.

GENERAL DESCRIPTION

The South boundary of the Township is located
about 9 miles North of Rye Patch Reservoir Dam.
The township drains Easterly into Rye Patch
Reservoir, which is located along the Easterly
portion of the township. Elevation ranges from
about 4,100 feet above sea level at the Westerly
edge of the Rye Patch Reservoir to about 5,300
feet above sea level along the spurs of the
Majuba Mountains located West of the township.

Access is by way of U.S. Interstate 80 Highway,
turning North at the Rye Patch Reservoir Dam
Interchange going across the dam, then North on
a graded road about 9 miles to the South bound-
ary of this township. The road continues
across the Easterly portion of the township
and continues Northerly to Nevada State High-
way 49.

There are scattered stands of juniper in the
Western portion of the township. Most of the
area is covered with medium growth of shadscale,
greasewood and budsage.

The principal use of this area is livestock
grazing. Public land areas are used for recrea-
tion by equestrians, campers, picnickers, boat-
ers and fishing.

There are no buildings in this area.

No minerals were noted along the lines surveyed.