

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
T. 13 N., R. 70 E., MDM, NEVADA

<p>CHAINS 41.06</p>	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, <math>2\frac{1}{2}</math> ins. diam., 16 ins. in the ground to bedrock and in a mound of stone, 4 ft. base to top, with brass cap mkd.</p> <p style="text-align: center;">T13N R70E <math>\frac{1}{4}</math> S 6 S 5</p> <p style="text-align: center;">1973</p>
<p>75.50</p>	<p>Fence, bears NE. and SW.</p>
<p>82.01</p>	<p>The cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the Tp.</p>
	<p style="text-align: center;">GENERAL DESCRIPTION</p> <p>The area resurveyed in this Township ranges from about 5,100 to 8,600 ft. above sea level. The town of Baker, Nevada is situated in section 9 of the township.</p> <p>There are scattered pinon and juniper in the southwestern portion of the township. The vegetation consists of sagebrush, greasewood, rabbitbrush and shadscale. The general drainage is northeast.</p> <p>Nevada Highway No. 73 enters the township on the east boundary of section 36 and leaves on the north boundary of section 5. Nevada Highway No. 74 enters the township on the west boundary of section 7 and ends at the town of Baker, Nevada. The township is supplemented by numerous trail roads.</p> <p>There are ranches and cultivated land in sections 3, 10, 11 and 15. No mineral formation of consequence were noted in the township.</p>