

SURVEY OF THE SUBDIVISIONAL LINES,
T. 29 N., R. 23 E., MDM, NEVADA

CHAINS	
40.00	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 6.</p> <p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T29N R23E $\frac{1}{4}$ S 6 S 5</p> <p style="text-align: center;">1979</p>
45.50	Low sand ridge, bears E. and W.
77.20	Ridge, bears E. and W.
79.77	<p>The cor. of secs. 5 and 6, on the N. bdy. of the Tp., monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set and exposed 4 ins. above the ground, with brass cap mkd. as described in the field notes of the survey of T. 30 N., R. 23 E., executed concurrently under this same group.</p> <p>Land, nearly level. Soil, sandy alkali. Undergrowth, sagebrush.</p> <hr/> <p style="text-align: center;">RETRACEMENT AND REMONUMENTATION OF CERTAIN CORNERS OF A PORTION OF MINERAL SURVEY NOS. 4036, 4323 AND 4324, MOUNT DIABLO MERIDIAN, NEVADA</p> <hr/> <p style="text-align: center;">Reestablishment of a Portion of Mineral Survey No. 4036, Executed by Thos L. Darby, U.S. Mineral Surveyor, in 1911 and Mineral Survey Nos. 4323 and 4324, Executed by Milton A. Pray, U.S. Mineral Surveyor, in 1917.</p> <hr/> <p>From Cor. No. 4 of M.S. No. 4324, Round Up Placer, monumented with a pine post, 4 ins. square, 36 ins. long, plainly scribed RU 4 4324 and loosely set in a mound of stone.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T29N R23E</p> <p style="text-align: center;">S 4</p> <p style="text-align: center;">COR 4 RU MS 4324 </p> <p style="text-align: center;">1979</p> <p>Reset the original wooden post alongside the iron post.</p>