

SURVEY OF THE SUBDIVISIONAL LINES,
T. 30 N., R. 23 E., MDM, NEVADA

CHAINS	
	<div style="text-align: center;">T30N R23E</div> <div style="text-align: center;">$\frac{1}{4}$ S 30</div> <div style="text-align: center;">$\frac{1}{4}$ S 31</div> <div style="text-align: center;">1979</div> <p>Raise a mound of stone, 3 ft. base, 2 ft. high, N. of cor.</p> <p>51.00 Improved graded road, bears NE. and SW.</p> <p>67.00 Improved graded road, on curve, bears NE. and W.</p> <p>74.98 The cor. of secs. 25, 30, 31 and 36, on the W. bdy. of the Tp., monumented with an iron post, 3 ins. diam., firmly set showing 4 ins. above the ground, with brass cap mkd. as described in the field notes of the survey of T. 30 N., R. 22 E., executed under Group No. 31.</p> <p>Land, nearly level. Soil, sandy alkali. Undergrowth, greasewood.</p> <hr/> <p>From the cor. of secs. 29, 30, 31 and 32.</p> <p>N. 0° 04' W., bet. secs. 29 and 30.</p> <p>Over nearly level land.</p> <p>21.20 Improved graded road, bears ENE. and WSW.</p> <p>36.80 Low ridge, bears E. and W.</p> <p>40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 29 and 30.</p> <p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;">T30N R23E</div> <div style="text-align: center;">$\frac{1}{4}$</div> <div style="text-align: center;">S 30 S 29</div> <div style="text-align: center;">1979</div> <p>Raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.</p> <p>From this corner, a U.S.G.S. Bench Mark, monumented with a standard tablet, stamped "3 DM 1963", firmly set in a concrete post, 6 ins. square, exposed 2 ins. above the ground, bears S. 45° 12' E., 21.42 chs. dist.</p> <p>80.00 Point for the cor. of secs. 19, 20, 29 and 30.</p> <p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.</p>