

142

DEPENDENT RESURVEY OF A PORTION OF
THE SUBDIVISIONAL LINES,
T. 40 N., R. 51 E., MDM, NEVADA

CHAINS

DEPENDENT RESURVEY OF A PORTION OF
THE SUBDIVISIONAL LINES,
T. 40 N., R. 51 E., MDM, NEVADA

Reestablishment of a Portion of the Survey Executed by
A.J. Hatch and J.H. Eaton, U.S. Deputy Surveyors,
in 1871.

From the cor. of secs. 2, 3, 34 and 35, on the S. bdy.
of the Tp., monumented with an iron post, $2\frac{1}{2}$ ins. diam.,
with brass cap mkd. as described in the field notes of
the dependent resurvey of T. 39 N., R. 51 E.,
concurrently resurveyed under this same Group.

N. $1^{\circ} 27'$ W., bet. secs. 34 and 35.

Over gently rolling land, through sagebrush.

- 1.50 Trail road, bears NW. and SE.
- 5.30 Bladed road, bears ENE. and WNW.
- 22.70 Trail road, bears NW. and SE.
- 31.51 Intersect line 4-5 of M.S. 1840, Blossom lode, at a
point from which:

Cor. No. 5, Blossom lode, identical with Cor. No.
2, Comfort lode, both of M.S. 1840, hereinafter
described, bears S. $81^{\circ} 42'$ E., 2.628 chs. dist.
- 39.64 Intersect line 1-2 of M.S. 4094, Phoenix lode, at a
point from which:

Cor. No. 2 of M.S. 4094, Phoenix lode, hereinafter
described bears N. $33^{\circ} 13'$ E., 6.037 chs. dist.
- 40.76 The $\frac{1}{4}$ sec. cor. of secs. 34 and 35, monumented with a
mound of stone, no marked stone found and with a steel
fence post firmly set alongside. This is accepted as
the best available evidence of the position of the
original corner.
- At the corner point
- Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins.
in the ground, with brass cap mkd.

T40N R51E

$\frac{1}{4}$

S 34|S 35

1981