## DEPENDENT RESURVEY OF THE SUBDIVISIONAL LINES, T. 22 N., R. 39 E., MDM, NEVADA

	1. 22 N., R. J. I., IIII, HUYADA
chains 6.60	Ridge, bears E. and W.
39.71	Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 6, at proportionated distance; there is no remaining evidence of the original corner.
	Set an aluminum post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground to solid rock and in a mound of stone, 3 ft. base to top, with aluminum cap mkd.
	T22N R39E
	$\begin{array}{cccccccccccccccccccccccccccccccccccc$
	1983
54.30	Wash, 25 lks. wide, 2 ft. deep, drains W.
79.21	The cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the Tp., monumented with an aluminum post, $2\frac{1}{2}$ ins. diam., firmly set, showing 6 ins. above the ground, with aluminum cap mkd. as described in the field notes of the dependent resurvey of T. 23 N., R. 39 E., executed concurrently under this same Group.
	GENERAL DESCRIPTION
	The land within Township 22 North, Range 39 East is about 5,200 to 7,100 ft. above sea level and is rolling to mountainous land. The soil is sandy clay loam along the bottom land and rocky on the high elevations. The land is covered with sagebrush, native grass and cheatgrass, with juniper and pinon pine in the higher elevations.
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	There is a graded gravel road entering in sec. 36 and leaving in sec. 19. There is also a graded gravel road entering in sec. 36 and leaving in sec. 24.
	Principal users of the area are ranchers.
	There were no mineral formation of consequence noted during the survey.