

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,  
T. 38 N., R. 62 E., MDM, NEVADA

CHAINS

T38N R62E  
S 31 | S 32  
S 6 | S 5  
T37N

1983

Reset the decayed remains of the original wooden post and steel fence post, alongside the iron post.

From this corner, a U.S.C. & G.S. Bench Mark, monumented with an iron pipe, 3 ins. diam., with a standard cap mkd. "P 4" riveted to the top, firmly set and exposed 12 ins. above the ground, bears N. 19° 05' E., 20.30 chs. dist.

N. 88° 28' W., bet. secs. 6 and 31.

Over rolling land, through scattered sagebrush.

3.30

Fence, bears N. and S.

40.64

Point for the  $\frac{1}{4}$  sec. cor. of secs. 6 and 31, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T38N R62E  
 $\frac{1}{4}$  S 31  
S 6  
T37N

1983

Set a steel fence post,  $5\frac{1}{2}$  ft. long, alongside the iron post.

81.28

The cor. of Tps. 37 and 38 N., Rs. 61 and 62 E., monumented with an aluminum post,  $2\frac{1}{2}$  ins. diam., firmly set showing 6 ins. above the ground, with aluminum cap mkd. as described in the field notes of the dependent resurvey of the east boundary of T. 37 N., R. 61 E., executed under Group No. 584.

DEPENDENT RESURVEY OF THE NORTH BOUNDARY,  
T. 38 N., R. 62 E., MOUNT DIABLO MERIDIAN, NEVADA

Reestablishment of a Portion of the Survey Executed by  
C. C. Tracy, U.S. Deputy Surveyor,  
in 1869,  
and Retracement and Survey Executed by T. K. Stewart,  
U.S. Deputy Surveyor, in 1883 and 1884.