

DEPENDENT RESURVEY OF A PORTION OF THE NORTH BOUNDARY,
T. 31 N., R. 57 E., MDM, NEVADA

CHAINS	
	<p>From this point, an iron post, 2 ins. diam., showing 18 ins. above ground, with a brass plate, 2X2 ins. on top, mkd. FWM & SON W 1/16 S6 1964, bears N. 14° 59' E., 0.41 chs. dist. This monument was established by F. W. Millard & Son, Registered Engineers and Land Surveyors, using improper procedures and is not utilized in the course of this survey.</p>
60.50	Fence, bears N. and S.
61.60	Trail road, bears N. and S.
79.90	Trail road, bears N. 20° E. and S. 20° W.
80.20	<p>The cor. of Tps. 31 and 32 N., Rs. 56 and 57 E., monumented with an iron post, 2½ ins. diam., firmly set in a collar of stone, with brass cap mkd. as described in the field notes of the dependent resurvey of the E. bdy., T. 31 N., R. 56 E., executed concurrently under this same Group.</p>
	<p>DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 31 N., R. 57 E., MOUNT DIABLO MERIDIAN, NEVADA</p>
	<p>Reestablishment of the Survey Executed by C. C. Tracy, U.S. Deputy Surveyor, in 1868, and the Completion Survey and Resurvey Executed by N. E. Potter, U.S. Surveyor, in 1915.</p>
	<p>From the cor. of secs. 10, 11, 14 and 15, monumented with an iron post, 2 ins. diam., firmly set in a mound of stone, with brass cap mkd. as described in the field notes of the survey of a portion of the subdivisional lines, T. 31 N., R. 57 E., executed under Group No. 20.</p> <p>Add the marks 1983 to the brass cap.</p> <p>N. 0° 03' W., bet. secs. 10 and 11.</p> <p>Over mountainous land, covered with scattered sagebrush.</p>
32.90	Spur, slopes W.
39.89	<p>The ¼ sec. cor. of secs. 10 and 11, monumented with an iron post, 1 in. diam., firmly set in a mound of stone, with brass cap mkd. as described in the field notes of the survey of a portion of the subdivisional lines, T. 31 N., R. 57 E., executed under Group No. 20.</p>