

DEPENDENT RESURVEY OF A PORTION OF  
THE SUBDIVISIONAL LINES,  
T. 39 N., R. 68 E., MDM, NEVADA

<p>CHAINS 40.66</p>	<p>The cor. of secs. 1, 2, 11 and 12, monumented with a wooden post, 3 ins. square, 36 ins. long, loosely set, with illegible scribe marks visible, with a steel fence post, 3 ft. long, firmly set and exposed 12 ins. above ground, alongside.</p> <p>At the corner point</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T39N R68E S 2 S 1 S 11 S 12</p> <p style="text-align: center;">1986</p> <p>Reset the original wooden post and steel fence post and set a steel fence post, 5 ft. long, alongside the stainless steel post.</p>
<p>36.80</p>	<p>N. 89° 40' E., bet. secs. 1 and 12.</p> <p>Over gently rolling land, through scattered sagebrush, greasewood and native grass.</p> <p>Trail road, bears NW. and SE.</p>
<p>41.01</p>	<p>The ¼ sec. cor. of secs. 1 and 12, monumented with a wooden post, 3 ins. square, 28 ins. long, firmly set and exposed 14 ins. above ground, plainly mkd. ¼ on N. face, with a steel fence post, 5½ ft. long, alongside.</p> <p>At the corner point</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T39N R68E S 1 ¼ S 12</p> <p style="text-align: center;">1986</p> <p>Reset the original wooden post and steel fence post alongside the stainless steel post.</p>
<p>43.00</p>	<p>S. 87° 58' E., beginning new measurement.</p> <p>Over gently rolling land.</p> <p>Charley Creek, 20 lks. wide, 1 ft. deep, drains SE.</p>
<p>50.65</p>	<p>Intersect the W. bdy. of sec. 6, T. 39 N., R. 69 E.</p> <p>The closing cor. of secs. 1 and 12, monumented with a steel fence post, 3½ ft. long, firmly set and exposed 36 ins. above ground. This steel fence post is accepted as a careful and faithful reestablishment of the position of the original corner.</p>