

DEPENDENT RESURVEY OF THE NORTH 5 MILES
OF THE EAST BOUNDARY,
T. 40 N., R. 69 E., MDM, NEVADA

CHAINS		
	N. 0° 08' W., bet. secs. 1 and 6.	
	Over rolling land, covered with scattered sagebrush, greasewood, rabbitbrush, juniper, and native grass.	
5.60	Trail road, bears ESE. and WNW.	
40.48	Point for the ¼ sec. cor. of secs. 1 and 6, at proportionate distance; there is no remaining evidence of the original corner.	
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.	
	<p style="text-align: center;">T40N R69E R70E ¼ S 1 S 6 1986</p>	
	Set a steel fence post, 5½ ft. long, alongside the stainless steel post.	
53.50	Wash, 20 lks. wide, 6 ft. deep, drains ESE.	
77.73	Intersect the Eighth Standard Parallel North.	
	Point for the closing cor. of Tps. 40 N., Rs. 69 and 70 E., at proportionate distance; there is no remaining evidence of the original corner.	
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.	
	<p style="text-align: center;">T41N R69E S 36 S 1 S 6 R69E R70E T40N CC 1986</p>	
	Set a steel fence post, 5½ ft. long, alongside the stainless steel post.	
	From this corner, the standard ¼ sec. cor. of sec. 36, T. 41 N., R. 69 E., hereinbefore described, bears N. 89° 22' E., 16.34 chs. dist.	
	From this same corner, a steel fence post firmly set and exposed 24 ins. above the ground, bears N. 11° 49' W., 1.67 chs. dist. This steel fence post as shown on map number 72034 on file at the offices of Kennedy, Jenks and Chilton in Elko, Nevada was improperly established using insufficient control and was not utilized in this survey.	