DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 32 N., R. 54 E., MDM, NEVADA

40.10	Spur, projects N.
40.70	The $\frac{1}{4}$ sec. cor. of secs. 1 and 12, monumented with a limestone, 15X10X6 ins., firmly set in a mound of stone, plainly mkd. $\frac{1}{4}$ on W. face.
	At the corner point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 16 ins. in the ground to solid rock and in a mound of stone, 3 ft. base to top, with brass cap mkd.
	T32N R54E S 1 ¹ / ₄ S 12
	1987
	Deposit the original cornerstone and set a steel fence post, $5\frac{1}{2}$ ft. long, alongside the stainless steel post.
	From this corner, a U.S.G.S. Bench Mark, monumented with a standard brass tablet, firmly set in concrete with brass tablet mkd. "11GWM 1951," bears N. 39° 39' W., 34.53 chs. dist.
	S. 89° 44' W., beginning new measurement.
	Over mountainous land.
8.70	Dixie Creek, 10 1ks. wide, 1 ft. deep, course NE.
11.00	Trail road, bears NE. and SW.
19.50	Improved gravel road, bears irregularly NNW. and SSE.; enter rolling land.
40.20	The cor. of secs. 1, 2, 11 and 12, monumented with a redwood post, 3 ins. square, 36 ins. long, firmly set 10 ins. in the ground, with illegible scribe marks visible and a steel fence post, $5\frac{1}{2}$ ft. long, firmly set alongside.
	At the corner point
	Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T32N R54E S 2 S 1 S 11 S 12
	1987
	Reset the original wooden post and steel fence post, alongside the stainless steel post.
	N. 0° 24' W., bet. secs. 1 and 2.
	Over rolling land, through scattered sagebrush, native grass and juniper.
	Ridge, bears E. and W.; enter railed area.