

478

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,
T. 33 N., R. 55 E., MDM, NEVADA

CHAINS

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,
T. 33 N., R. 55 E., MOUNT DIABLO MERIDIAN, NEVADA

Reestablishment of the Survey Executed by
A. J. Hatch, W. W. Skinner and C. S. Preble,
U.S. Deputy Surveyors, in 1874,
and
the Survey Executed by
H. B. Maxson, U.S. Deputy Surveyor,
in 1896.

From the cor. of secs. 3, 4, 33 and 34, on the S. bdy.
of the Tp., monumented with an iron pipe, 2 ins. diam.,
firmly set showing 6 ins. above the ground, with brass
cap mkd. T33N R55E S33 S34 S4 S3 T32N 1974 RLS 2455.
This monument was established by A. S. Boyack,
Registered Land Surveyor, and was recorded in the Elko
County Court House under File No. 86881. This iron
pipe is accepted as a careful and faithful perpetuation
of the position of the original corner. This monument
meets the standards set by the Bureau and was not
remonumented. Add the marks BLM 1987 to the brass cap.

From this corner, U.S.C. & G.S. triangulation station
PORTER, monumented with a standard brass tablet firmly
set in bedrock, with brass tablet mkd. "PORTER 1947,"
bears S. 16° 20' W. (mean bearing), 206.76 chs. dist.

N. 89° 36' W., bet. secs. 4 and 33.

Over rolling land, through scattered sagebrush and
native grass.

5.60 Spur, projects S.

39.00 Wash, 15 lks. wide, 2 ft. deep, drains S.

39.48 Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 33, at
proportionate distance; there is no remaining evidence
of the original corner.

Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins.
diam., 24 ins. in the ground, with brass cap mkd.

T33N R55E
S 33
 $\frac{1}{4}$ $\frac{S}{4}$
T32N

1987

Set a wooden post, 3 ins. square, 4 ft. long, alongside
the stainless steel post and raise a mound of stone, 3
ft. base, 2 ft. high, N. of cor.

68.10 Ravine, drains SE.