## DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 17 S., R. 65 E., MDM, NEVADA

CHAINS

From the  $\frac{1}{4}$  sec. cor. of secs. 9 and 10, monumented with an iron post,  $2\frac{1}{2}$  ins. diam., firmly set in a mound of stone, with brass cap mkd. as described in the field notes of the independent resurvey of T. 17 S., R. 65 E., executed under Group No. 373.

N.  $0^{\circ}$  01.9' W., bet. secs. 9 and 10.

Over gently rolling land, covered with scattered chaparral, creosote brush and cacti.

26.633

Intersect the Fourth Standard Parallel South.

Point for the closing cor. of secs. 9 and 10.

Set an aluminum post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with aluminum cap mkd.

T16S R65E S 33 S 9|S 10 C C T17S R65E

1986

Set a steel fence post,  $5\frac{1}{2}$  ft. long, alongside the aluminum post.

From this corner, the standard  $\frac{1}{4}$  sec. cor. of sec. 33, T. 16 S., R. 65 E., monumented with an aluminum post,  $2\frac{1}{2}$  ins. diam., firmly set showing 4 ins. above ground, with aluminum cap mkd. as described in the field notes of the dependent resurvey of T. 16 S., R. 65 E., executed concurrently under this same Group, bears N. 89° 24.2' E., 10.514 chs. dist.

From this same corner, the closing cor. of secs. 9 and 10, monumented with an iron post,  $2\frac{1}{2}$  ins. diam., firmly set in a mound of stone, with brass cap mkd. as described in the field notes of the independent resurvey of T. 17 S., R. 65 E., executed under Group No. 373, bears N. 0° 01.9' W., 2.761 chs. dist. Hereafter, this cor. will function as an amended monument.

Add the marks "AM 1986" to the brass cap.

from which

The standard cor. of secs. 32 and 33, T. 16 S., R. 65 E., monumented with an iron post, 2 ins. diam., firmly set showing 6 ins. above ground, with brass cap mkd. as described in the field notes of the independent resurvey of T. 16 S., R. 65 E., executed under Group No. 237, bears N.  $89^{\circ}$  58.0' W., 11.877 chs. dist. Hereafter, this cor. will function as an amended monument.

Add the marks "AM 1986" to the brass cap.