

155

DEPENDENT RESURVEY OF THE SUBDIVISIONAL LINES,  
T. 31 N., R. 55 E., MDM, NEVADA

CHAINS

T31N R55E

S 6<sup>1</sup>/<sub>4</sub> S 5

1987

Reset the original wooden post and set a steel fence post, 5½ ft. long, alongside the stainless steel post.

N. 0° 33' W., beginning new measurement.

Over rolling land.

- 28.10 Wash, 50 lks. wide, 10 ft. deep, drains NW.
- 32.10 Improved road on curve, bears N. and SE.
- 38.50 Improved road, bears NNE. and SSW.
- 40.12 The cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the Tp.

## GENERAL DESCRIPTION

The area resurveyed within Township 31 North, Range 55 East, varies from mountainous in the central portion to rolling in the west portion with the east portion being nearly level. The elevation ranges from about 5,300 to 6,400 ft. above sea level. The soil varies from sandy clay loam and rocky on the higher elevations to sandy clay loam on the bottom land. The vegetation consists of sagebrush, rabbitbrush, crested wheatgrass and native grass. There are light to heavy stands of juniper and pinon pine throughout the township.

Huntington Creek drains the east portion of the township in a northerly direction. Also, the western portion of the township is drained northerly by a major wash. Indian Well is located in section 30 and Red Spring is located in section 16.

Principal users of the area are cattlemen. Access into the township is provided by improved and unimproved roads. No mineral formations of consequence were noted.